

Troubleshooting

Drilling

Difficulties	Root causes
Tapered drill holes	<ul style="list-style-type: none">-Incorrectly sharpened drill bits-Insufficient play / clearance-Excessively high feed rate
Burnt or melted surface	<ul style="list-style-type: none">-Use of unsuitable drill bits-Incorrectly sharpened drill bits-Insufficient feed rate-Blunt drill bit-Land too thick
Surface flaking	<ul style="list-style-type: none">-Excessive feed rate-Excessive play / clearance-Excessive incline (thin land as described)
Chatter marks	<ul style="list-style-type: none">-Excessive play / clearance-Insufficient feed rate-Drill overhang too great-Excessive incline (thin land as described)
Feed marks or spiral lines at the inside diameter	<ul style="list-style-type: none">-Excessively high feed rate-Drill not centred-Drill tip not in centre
Overdimensioned drill holes	<ul style="list-style-type: none">-Drill tip not in centre-Land too thick-Insufficient play / clearance-Excessively high feed rate-Drill point angle too great
Underdimensioned drill holes	<ul style="list-style-type: none">-Blunt drill bit-Excessive play / clearance-Drill point angle too small

Difficulties	Root causes
Unconcentric drill holes	<ul style="list-style-type: none"> -Excessively high feed rate -Spindle speed too low -Drill penetrates too far into next part -Parting-off tool leaves "stump" which deflects the drill bit -Land too thick -Drilling speed too high at the start -Drill not clamped centrally -Drill not correctly sharpened
Burr left after parting off	<ul style="list-style-type: none"> -Blunt cutting tool -Drill does not travel completely through the part
Drill quickly becomes blunt	<ul style="list-style-type: none"> -Feed rate too low -Spindle speed too low -Insufficient lubrication due to cooling

Turning and milling

Difficulties	Root causes
Surface has started to melt	<ul style="list-style-type: none"> -Blunt tool or shoulder friction -Insufficient lateral play / clearance -Feed rate too low -Spindle speed too high
Rough surface	<ul style="list-style-type: none"> -Feed rate too high -Incorrect clearance -Sharp point at the tool (slight spur radius required) -Tool not centrally mounted
Burr on corners of cutting edge	<ul style="list-style-type: none"> -No space in front of the cutting diameter -Blunt tool -Insufficient lateral play / clearance -No lead angle at the tool
Cracks or flaking at the corners	<ul style="list-style-type: none"> -Too much positive inclination at the tool -Tool approaches material with too much force (impact too high) -Blunt tool -Tool mounted under the centre

Difficulties	Root causes
--------------	-------------

-Sharp point at the tool (slight spur radius required)

Chatter marks

- Excessive spur radius at the tool
- Tool not sufficiently firmly mounted
- Insufficient material guidance
- Cutting edge width too great (use 2 cuts)

Parting off/sawing

Difficulties	Root causes
--------------	-------------

Surface has started to melt

- Blunt tool
- Insufficient lateral play / clearance
- Insufficient coolant feed

Rough surface

- Feed rate too high
- Tool unprofessionally sharpened
- Cutting edge not honed

Spiral marks

- Tool friction during withdrawal
- Burr on the tool

Concave and convex surfaces

- Point angle too great
- Tool not vertical relative to the spindle
- Tool is deflected
- Feed rate too high
- Too mounted above or below the centre

"Stumps" or burr at the end of the cutting surface

- Point angle not large enough
- Blunt tool
- Feed rate too high

Burr on the outside diameter

- Blunt tool
- No space in front of the cutting diameter